


6300
12 12 12
12 12 12

FIG. 4A



CHANGE HATCHING
FROM METAL TO THAT
FOR REFRACTORY
MATERIAL

FIG. 4B

